



# the **play inspection** company

---

## Annual Inspection

Winchester City Council

Arlebury Park, Skate Park & Tennis(New Alresford)

The Avenue, Alresford, SO24 9EP



**API** Associate



Unit 5, Glenmore Business Park, Blackhill Road, Poole, Dorset, BH16 6NL  
t- 01202 590675 e- info@playinspections.co.uk

[www. playinspections .co.uk](http://www.playinspections.co.uk)

## Inspection Scope for RPII Inspection Methodology

This document outlines the RPII scope for inspections undertaken by the Inspectors listed as Annual Inspectors on the RPII Register of Inspectors when undertaking Indoor Annual, Outdoor Annual, Outdoor Operational and Outdoor Routine inspections.

Inspections are undertaken with reference to the standards listed in this preamble only; where no date for the standard is given it will be the standard that is current at the time of inspection except where overlap periods are granted by the standards committee when standards are updated. The information contained in reports is provided to assist the owner/operator in fulfilling their responsibilities as detailed in the relevant standard. Other standards referenced within the listed standards do not form part of the inspection, unless they are also explicitly listed here.

The following standards are relevant to all installations of equipment that are publicly accessible to users; this includes public parks, pay and play parks, schools, nurseries, public houses, holiday parks, indoor play centres, farm parks etc. All equipment used or employed in publicly accessible areas should meet with the requirements of the relevant standards (listed below):

BS EN 1176 Parts 1, 2, 3, 4, 5, 6, 10 & 11 Playground equipment intended for permanent installation outdoors & indoors.

BS EN 1176 Part 7 - 'Guidance on Installation, Inspection, Maintenance and Operation' (this document gives guidance to the owners/operators of the facility on the installation, inspection, maintenance and operation of playground equipment, excluding ancillary items).

In the United Kingdom the National Foreword forms an important part to the understanding and implementation of the recommendations set out in this document. It clarifies the application of the document within the UK as best practice guidance, as the document has been used since its initial publication. Therefore, in the UK this standard (BS EN 1176 – Part 7) contains no requirements and needs to be read and implemented as guidance, with the use of the term 'shall' therefore becoming a recommendation, as in the term 'should'.

Domestic play equipment falls outside of the scope of BS EN 1176 and has its own standards (BS EN 71 series – Safety of Toys). Where domestic equipment can be identified this will be acknowledged in the report but any comments concerning compliance will follow the requirements and recommendations of BS EN 1176.

When water play items, including spray parks, are inspected any comments concerning compliance within the inspection will refer to BS EN 1176. We have not assessed these against the requirements of BS EN 17232 (Water play equipment and features).

Other equipment that is not clearly identified as unsupervised or domestic (natural play, self-build equipment etc.) will be assessed for compliance with the relevant standard listed below:

**BS EN 15312** Free access multi-sports equipment  
**BS EN 14974** Skateparks  
**BS EN 16630** Permanently installed outdoor fitness equipment  
**BS EN 16899** Parkour equipment (plus RPII/API guidance notes)

Annual and Post Installation inspections will take into consideration compliance with these current standards, and defects related to wear and vandalism. Items not listed in the report have not been included in the inspection. The inspection will cover the playground equipment and the active area (that area which is obviously part of the playground), nominally up to three metres around, the fence line if closer, or other areas as agreed.

Operational inspections only take into consideration defects related to cleanliness, equipment ground clearances, ground surface finishes, exposed foundations, sharp edges, missing parts, excessive wear (of moving parts) structural integrity, wear and vandalism.

Routine visual inspections relate only to the most obvious defects such as broken or missing parts, litter, vandalism and issues created by severe weather conditions (the intention is to identify hazards created by storm damage).

All inspections are non-dismantling, non-destructive and do not include any structural, toxicology or impact assessments defined in the standard; however, the inspector will undertake a manual test for stability and if equipment fails under manual load, or any other hazard is identified as an unacceptable risk, the owner/operator will be notified as soon as practicably possible.

The inspector will access all reasonably accessible equipment and will assess all reasonably accessible parts above the standing surface. Where it is not possible to access parts of the equipment without employing an alternative means of access the report will record the action required by the owner/operator to ensure the continued safe use of the equipment.

Ancillary equipment will be assessed using the inspector's knowledge and experience of the standards named in this document. (Note: Ancillary items are not included in the specific equipment-type parts of the EN 1176 series; hence they are not assessed for compliance with EN 1176 series and are subject to a general safety assessment).

The owner/operator is responsible for the overall safety of the equipment and area.

The inspector will not undertake any of the following works unless specifically agreed in writing at the time of order:

Checking the depth and underlying structural integrity of any surface areas and/or carrying out any testing of the impact attenuating properties of any surfaces; the identification of any corrosion, rot or other deterioration in any apparatus or equipment other than by an external inspection; the inspection of any equipment (or part thereof) that is beneath the playing surface (loose-fill materials may be moved to expose foundations); tightening any bolts, hinges or other fixing devices on any apparatus or equipment; assessing or inspecting any electrical installations contained on any site and/or apparatus and/or equipment; assessing or inspecting any water supplies and/or water features and/or any associated computerised systems (including carrying out any programming); where planting or trees are mentioned in the report no assessments of toxicity, suitability or condition are undertaken – the owner/operator should have suitable inspections provided by a competent person.

The owner/operator should have a 'design risk assessment' provided by the manufacturer/designer of the area for the equipment and location in which the facility is installed.

The operator is responsible for managing risks of their provision and is required by law to carry out a 'suitable and sufficient assessment' of the risks associated with a site or activity. This inspection shall be considered as contributing to the operator's discharge of this responsibility.

The details contained within the report are a snapshot of the condition at the time of inspection only and subsequent events may affect the condition of the facility. Suggested remedial actions are based on the knowledge and experience of the inspector and/or that of the inspection company. The owner/operator should always seek the advice of the manufacturer or a competent person when undertaking repairs and/or modifications to equipment.

A full copy of the Play Inspection Company Ltd. Terms & Conditions is available on our website ([www.playinspections.co.uk](http://www.playinspections.co.uk))

The operator is responsible for following the guidance of the relevant standards. The standards give guidance on the installation, inspection, maintenance and operation of the various types of facilities. The inspection guidance is listed in Table 1, with an indication of which parts will be included in an RPII Annual or Post-Installation Inspection. The relevant standards also contain additional parts which the operator should follow.

Inspection recommendations of relevant standards Refer to relevant standards for full text	Annual Main	RPII Annual/ Post Installation Inspection
6.1 d) Overall levels of safety of equipment (see note 1)	✓	✓ [1]
6.1 d) Overall levels of safety of foundations (see note 1)	✓	✓ [1]
6.1 d) Overall levels of safety of playing surfaces (see note 2)	✓	✓ [2]
6.1 d) Compliance with the relevant parts of the standard and or risk assessment (see note 3)	✓	✓ [3]
6.1 d) Effects of weather	✓	✓
6.1 d) Presence of rot, decay or corrosion (see note 1)	✓	✓ [1]
6.1 d) Assessment of repairs made or added or replaced components (see note 4)	✓	✓ [4]
6.1 d) Excavation or dismantling/additional measures	✓	✗
6.2.1 Assessment of glass reinforced plastics (see note 5)	✓	✓ [5]
6.2.1 Inspection of one post equipment (see note 1)	✓	✓ [1]
6.2.4 Undertaking the Operators inspection protocol	✓	✗

NB: The clause numbers in table 1 are taken from BS EN 1176 - Part 7:2020. The content is equally applicable to all other relevant standards listed herein. Playgrounds contain a range of equipment from different manufacturers and installed over a number of years; operators should implement any guidance provided by the manufacturer. Item specific detail is not readily available to RPII Playground Inspectors, whose report contributes to the operator's overall Annual Main Inspection as detailed in the relevant standards.

[1] A manual test only is undertaken for stability. Wear and instability are only detectable where readily apparent without dismantling or destruction and without the use of tools, excavation or specialist equipment. Rot and corrosion are tested or with a hammer and/or steel rod. Decay in timber may exist which can only be found with specialist equipment.

[2] Only the visible condition and dimensional compliance of surface extent is considered. Neither testing of impact attenuating properties nor measurement of the thickness of bound surfaces are undertaken on RPII annual inspections.

[3] The inspection assesses compliance where this can be tested on site using manual methods without dismantling, destruction and without the use of tools or specialist equipment.

[4] The operator should use manufacturer's recommended parts, or equivalent. We are unable to verify if such parts have been used, and any subsequent change in quality or performance.

[5] Visible glass fibres will be noted in reports. The operator is responsible for repairs or replacement.

# Risk Assessment Matrix

			Scores in the report are multiplication factors of Likelihood x Severity					
			Severity>>					
<b>Likelihood</b>	Very High probability, if the situation is not addressed an accident is almost certain.	5	Very High	VL (5)	L (10)	M (15)	H (20)	VH (25)
	High probability an accident is probable without any added factor.	4	High	VL (4)	L (8)	M (12)	H (16)	H (20)
	Moderate probability an incident is foreseeable.	3	Moderate	VL (3)	L (6)	L (9)	M (12)	M (15)
	Some probability, requires a combination of factors to take place.	2	Low	VL (2)	VL (4)	L (6)	L (8)	L (10)
	No significant probability; lightning strike, freak accident.	1	Very Low	VL (1)	VL (2)	VL (3)	VL (4)	VL (5)
			Very Low	Low	Moderate	High	Very High	
			1	2	3	4	5	
			No injury likely e.g. damaged or soiled clothing, minor bruising, grazes	Minor injury, laceration or bruising requiring first aid only	Injury requiring medical intervention e.g. cuts requiring stitches	Serious injury including concussions or fracture of long bones	Severe injury involving a potential life changing injury or fatality	
			<b>Severity&gt;&gt;</b>					
<p>Note 1: The total risk scores included within our reports are a multiplication factor of the calculated Likelihood and Severity of each finding. Both Likelihood and Severity are given a number between 1 - 5 as shown on the matrix above and these two numbers are then multiplied together to give the total risk score that is shown against defects on the report. Total risk scores can be divided in both directions, i.e. a total risk score of 12 could be a Likelihood (3) x Severity (4) or Likelihood (4) x Severity (3).</p> <p>Note 2: When we inspect we only see a snapshot of the current condition of the equipment. It is the operators responsibility to ensure that there is a continuing level of maintenance to keep the equipment in good working order and the site fit for use.</p>								

**Equipment has been assessed to the following standards where relevant:**

- BS EN 1176 Parts 1-11 (Playground equipment and surfacing)
- BS EN 14974 (Facilities for users of roller sports equipment)
- BS EN 15312 (Free access multi-sports equipment)
- BS EN 16899 (Parkour Equipment)
- BS EN 16630 (Outdoor Fitness Equipment).

# Arlebury Park, Skate Park & Tennis(New Alresford)

Inspection Ref: 2694076

Site Ref: 48013

Inspected: 28-April-2025 - 07:47 by Leon Pope (RPII Annual Inspector)

Risk Assessment: 12 Moderate Risk

**Location:**

There are no specific notes for this site

**Disabled Access:**

Some accessible features; an area that presents difficulties to the majority of people with disabilities but in favourable circumstances and certainly in partnership can be accessed.

**i 9 - Low Risk**

**Item:** Site General  
**Manufacturer:** Owner/Operator  
**Surface Type:** N/A  
**Item Quantity:** 1  
**Equipment Compliance:** N/A  
**Surface Area Compliance:** N/A



**Total Findings:** 3

**Finding 1**

There is a discarded breeze block within the play area - Remove from site

**Finding 2**

The pathway to the skatepark has eroded and is slippery, making egress via this path extremely difficult - Reinstate eroded area

**Finding 3**

There is some graffiti present on the skate ramps - Remove the graffiti if deemed appropriate

**i 2 - Very Low Risk**

**Item:** Sign  
**Manufacturer:** Not Identified  
**Surface Type:** N/A  
**Item Quantity:** 1  
**Equipment Compliance:** N/A  
**Surface Area Compliance:** N/A



**Total Findings:** 1

**Finding 1**

This item is satisfactory - no work required -

**i** 8 - Low Risk

**Item:** Gate - Self Closing  
**Manufacturer:** Not Identified  
**Surface Type:** Mixed Surface  
**Item Quantity:** 3  
**Equipment Compliance:** N/A  
**Surface Area Compliance:** N/A



**Total Findings:** 4

**Finding 1**

There are openings that are less than 12mm that could trap or crush fingers - Provide a 12mm gap throughout full range of motion at both sides of gate

**Finding 2**

There is / are post or end caps missing / damaged on the item - Replace missing / damaged post or end caps

**Finding 3**

The gate is closing too quickly (less than 4 seconds) - Take corrective action to ensure that the gate closes in 4-8 seconds from 90 degrees

**Finding 4**

The rubber buffer is missing from the latch plate - Replace rubber buffer

**i** 8 - Low Risk

**Item:** Fencing - Timber  
**Manufacturer:** Not Identified  
**Surface Type:** Grass  
**Item Quantity:** 1  
**Equipment Compliance:** N/A  
**Surface Area Compliance:** N/A



**Total Findings:** 3

**Finding 1**

There are a number of loose posts around the fence - Monitor for any further deterioration and reset as required

**Finding 2**

Parts of the timber are rough or splintered - Remove all rough or sharp edges

**Finding 3**

There are areas or parts of the timber on the structure that have rotted - Replace all affected timbers

**i** 8 - Low Risk

**Item:** Fence - Chainlink  
**Manufacturer:** Not Identified  
**Surface Type:** Grass  
**Item Quantity:** 1  
**Equipment Compliance:** N/A  
**Surface Area Compliance:** N/A



**Total Findings:** 2

**Finding 1**

The fence is severely damaged in places - Repair or replace all affected sections

**Finding 2**

There are redundant cable ties attached to the fencing - Remove

**i** 8 - Low Risk

**Item:** Bench  
**Manufacturer:** Not Identified  
**Surface Type:** Grass  
**Item Quantity:** 1  
**Equipment Compliance:** N/A  
**Surface Area Compliance:** N/A



**Total Findings:** 1

**Finding 1**

The area around the item has eroded and may become slippery - Reinstate eroded area

**i** 6 - Low Risk

**Item:** Activity Trail  
**Manufacturer:** Dylan Group Ltd  
**Surface Type:** Mixed Surface  
**Item Quantity:** 1  
**Equipment Compliance:** Yes  
**Surface Area Compliance:** Yes



**Total Findings:** 2

**Finding 1**

There is/are bolt cap covers missing or damaged on the item - Replace missing or damaged bolt cap covers

**Finding 2**

The surface has eroded in some areas and may be slippery in wet conditions - Reinstate the surface

**i** 4 - Very Low Risk

**Item:** Swing Barrier  
**Manufacturer:** Wicksteed Playgrounds  
**Surface Type:** Grass  
**Item Quantity:** 2  
**Equipment Compliance:** N/A  
**Surface Area Compliance:** N/A



**Total Findings:** 1

**Finding 1**

This item is satisfactory - no work required -

**i** 8 - Low Risk

**Item:** 2 Bay (2 Flat, 2 Cradle)  
**Manufacturer:** Wicksteed Playgrounds  
**Surface Type:** Mixed Surface  
**Item Quantity:** 1  
**Equipment Compliance:** No  
**Surface Area Compliance:** No



**Total Findings:** 21

**Finding 1**

There are gaps opening between the grass mat tiles - Provide additional ties or secure / reinstate surface

**Finding 2**

The grass mats are silted up and the soil is compacted; this may have an effect on the impact absorbing properties of the surface. Consideration should be given to HIC testing the surface to verify impact attenuating properties ( <https://playinspections.co.uk/inspection-services/safety-surface-testing/> ) - Contact our office for a quotation for this service

**Finding 3**

The surface has subsided in some areas - Monitor for any further deterioration and repair as required

**Finding 4**

The surfacing dimensions are short and do not meet with the requirements of the current applicable standard - Monitor - No action given the risk assessment

**Finding 5**

The adjacent foliage is encroaching into the falling space of the equipment - Cut back and maintain

**Finding 6**

The tree root forms a hard object within the impact area of the equipment in contravention of the requirements of BS EN 1176 Part 1 - Monitor - No action given the risk assessment

**Finding 7**

BS EN 1176 requires an additional 0.5m of unobstructed space at each end of the swing surfacing area. This is a relatively low risk finding and no remedial action is recommended at this point. - Monitor - No action given the risk assessment

**Finding 8**

The seat/s is / are too close to the frame as defined in BS EN 1176 Part 2 - Monitor - No action given the risk assessment

**Finding 9**

The chain openings are in excess of the 8.6mm as recommended by BS EN 1176 - Monitor - No action given the risk assessment

**Finding 10**

The seats are too close to each other as defined in BS EN 1176 Part 2; this is a low risk failure and no remedial action is required - Monitor - No action given the risk assessment

**Finding 11**

The tree canopy overhangs the equipment and is less than 2.0m away - Lift tree canopy to ensure a minimum clearance of 2.0m from the equipment

**Finding 12**

The paint is flaking off the metalwork - Rub down and re-paint



<b>Finding 13</b> There is some notable evidence of chain wear - Monitor for any further deterioration and replace when 40% worn	<b>Finding 14</b> There is some wear to the connecting links - Monitor for any further deterioration and replace when 40% worn
<b>Finding 15</b> There is some wear to the chain bars - Monitor for any further deterioration and replace when 40% worn	<b>Finding 16</b> The bush / bushes is / are worn or missing - Replace worn or missing bushes
<b>Finding 17</b> There is some wear to the shackles. - Monitor for any further deterioration and replace when 40% worn	<b>Finding 18</b> There are excessive chain tails - Cut back excessive chain links
<b>Finding 19</b> There are excessive chain tails provided, however a minimum of 2 additional links should always be provided with crucifix connectors - Cut back excess chain tails but ensure a minimum of 2 additional links remain through the crucifix	<b>Finding 20</b> Cable ties are present and there are sharp projecting ends - Remove
<b>Finding 21</b> The fixings or components for this item were in excess of 2.5m above the standing surface and could not be fully accessed by the inspector. We have completed a visual inspection of the fixings from ground level but a maintenance inspection should be undertaken to assess the condition, security and wear of the components at intervals in accordance with the manufacturers recommendations. - Inspect in accordance with the manufacturers recommendations	

**i** 10 - Low Risk

**Item:** Boat  
**Manufacturer:** Not Identified  
**Surface Type:** Grass  
**Item Quantity:** 1  
**Equipment Compliance:** Yes  
**Surface Area Compliance:** Yes



**Total Findings:** 5

**Finding 1**

The surface has eroded in some areas and may be slippery in wet conditions - Reinstate the surface

**Finding 2**

There is some evidence of fire damage to the item - Monitor for any further deterioration and repair as required

**Finding 3**

There are areas or parts of the timber on the structure that have rotted - Replace all affected timbers

**Finding 4**

There is some evidence of rot in the timber - Monitor for any further deterioration and replace as required

**Finding 5**

The decking is damaged exposing ground fixings - Repair affected areas

**i** 8 - Low Risk

**Item:** Free Standing Slide  
**Manufacturer:** Wicksteed Playgrounds  
**Surface Type:** Grass Matrix Tiles  
**Item Quantity:** 1  
**Equipment Compliance:** No  
**Surface Area Compliance:** Yes

**Total Findings:** 5



**Finding 1**

The grass mats are silted up and the soil is compacted; this may have an effect on the impact absorbing properties of the surface. Consideration should be given to HIC testing the surface to verify impact attenuating properties ( <https://playinspections.co.uk/inspection-services/safety-surface-testing/> ) - Contact our office for a quotation for this service

**Finding 2**

Fixing Pins have been installed in the impact areas of the grass mats - Remove pins from impact areas

**Finding 3**

There are gaps opening between the grass mat tiles - Provide additional ties or secure / reinstate surface

**Finding 4**

The paint is flaking off the metalwork - Rub down and re-paint

**Finding 5**

There is / are toggle entrapment/s present in contravention of the recommendations set out in BS EN 1176 Part 1 - Monitor - No action given the risk assessment

**i** 8 - Low Risk

**Item:** Spring See-Saw  
**Manufacturer:** Kompan Ltd  
**Surface Type:** Mixed Surface  
**Item Quantity:** 1  
**Equipment Compliance:** Yes  
**Surface Area Compliance:** Yes

**Total Findings:** 4



**Finding 1**

The grass has eroded within the impact area of the equipment and may not provide the necessary impact attenuating properties for the equipment fall height; the surface may also be slippery in wet weather - Reinstate the grass or provide an all weather surface

**Finding 2**

The surfacing has numerous stones present - Ensure stones are removed and ground is suitable for use

**Finding 3**

There is/are bolt cap covers missing or damaged on the item - Replace missing or damaged bolt cap covers

**Finding 4**

The spring mounting plate is slightly loose in the ground - Monitor for any further deterioration and repair as required

**i** 10 - Low Risk

**Item:** Multi Play (Junior)  
**Manufacturer:** Not Identified  
**Surface Type:** Grass Matrix Tiles  
**Item Quantity:** 1  
**Equipment Compliance:** No  
**Surface Area Compliance:** Yes



**Total Findings:** 20

**Finding 1**

There are falls in excess of 600mm between adjacent components on the structure, in contravention of the recommendations set out in BS EN 1176 Part 1; 4.2.8.4 - Monitor - No action given the risk assessment

**Finding 2**

The item fails to meet the requirements of BS EN 1176 Part 1 4.2.7.2 for head and neck entrapment between the log climber - Consider removing entrapments

**Finding 3**

There is/are finger entrapment/s above the net climber and the item fails to meet the requirements of BS EN 1176 Part 1 4.2.7.6 Entrapment of fingers - Monitor - No action given the risk assessment

**Finding 4**

The connecting links are in excess of 8.6mm and less than 12mm and fail the requirements of BS EN 1176 Part 1; clause 4.2.13, Chains - Monitor - No action given the risk assessment

**Finding 5**

The item fails to meet the requirements of BS EN 1176 Part 1 4.2.7.2 head and neck entrapment in the barriers and/or steps - Monitor - No action given the risk assessment

**Finding 6**

The grass mats are silted up and the soil is compacted; this may have an effect on the impact absorbing properties of the surface. Consideration should be given to HIC testing the surface to verify impact attenuating properties ( <https://playinspections.co.uk/inspection-services/safety-surface-testing/> ) - Contact our office for a quotation for this service

**Finding 7**

There are gaps opening between the grass mat tiles - Provide additional ties or secure / reinstate surface

**Finding 8**

The surface has subsided in some areas - Monitor for any further deterioration and repair as required

**Finding 9**

The rope has worn and wire strands are exposed - Replace rope or net

**Finding 10**

There is some wear to the shackles. - Monitor for any further deterioration and replace when 40% worn

**Finding 11**

The chain links are worn excessively (50%) and require renewing - Replace worn chains

**Finding 12**

The paint is flaking off the metalwork - Rub down and re-paint

**Finding 13**

The tree canopy overhangs the equipment and is less than 2.0m away - Lift tree canopy to ensure a minimum clearance of 2.0m from the equipment

**Finding 14**

There is some notable evidence of chain wear - Monitor for any further deterioration and replace when 40% worn

<b>Finding 15</b>	<b>Finding 16</b>
The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting / corroding - Treat affected areas and repaint	There is some evidence of rot in the timber - Monitor for any further deterioration and replace as required
<b>Finding 17</b>	<b>Finding 18</b>
The connecting lugs are showing signs of wear - Monitor for any further deterioration and repair as required	The timber has a number of splits/shakes or air cracks and this may affect the stability or allow water ingress which will accelerate the rotting process - Monitor to ensure the splits do not cross through fixing points of the structure and/or cause any instability
<b>Finding 19</b>	<b>Finding 20</b>
Parts of the timber are rough or splintered - Remove all rough or sharp edges	The fixing plates are not flush with the posts - Rectify installation

10 - Low Risk	
<p><b>Item:</b> Climbing Frame  <b>Manufacturer:</b> Not Identified  <b>Surface Type:</b> Grass  <b>Item Quantity:</b> 1  <b>Equipment Compliance:</b> No  <b>Surface Area Compliance:</b> Yes</p> <p><b>Total Findings:</b> 4</p>	
<b>Finding 1</b>	<b>Finding 2</b>
The surface has subsided in some areas - Monitor for any further deterioration and repair as required	The surface has eroded and the foundations are exposed - Reinstate surrounding surfaces to cover the foundations
<b>Finding 3</b>	<b>Finding 4</b>
The item fails to meet the requirements of BS EN 1176 Part 1 4.2.7.2 for head and neck entrapment in the framework - Monitor - No action given the risk assessment	The paint is flaking off the metalwork - Rub down and re-paint

**!** 12 - Moderate Risk

**Item:** Overhead Glider  
**Manufacturer:** Not Identified  
**Surface Type:** Grass Matrix Tiles  
**Item Quantity:** 1  
**Equipment Compliance:** No  
**Surface Area Compliance:** Yes

**Total Findings:** 9



**Finding 1**

The surface has eroded and the foundations are exposed - Reinstate surrounding surfaces to cover the foundations

**Finding 3**

The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting / corroding - Treat affected areas and repaint

**Finding 5**

The connecting links are worn excessively (70%) and require renewing - Replace

**Finding 7**

There is some wear to the chain bars - Monitor for any further deterioration and replace when 40% worn

**Finding 9**

There is/are finger entrapment/s in the traveller and the item fails to meet the requirements of BS EN 1176 Part 1 4.2.7.6 Entrapment of fingers - Monitor - No action given the risk assessment

**Finding 2**

There are gaps opening between the grass mat tiles - Provide additional ties or secure / reinstate surface

**Finding 4**

The paint is flaking off the metalwork - Rub down and re-paint

**Finding 6**

There is some notable evidence of chain wear - Monitor for any further deterioration and replace when 40% worn

**Finding 8**

There is or are fixings missing on the item - Replace all missing fixings

**i 8 - Low Risk**

**Item:** Teenage Shelter  
**Manufacturer:** Monster Play Systems  
**Surface Type:** Grass  
**Item Quantity:** 1  
**Equipment Compliance:** N/A  
**Surface Area Compliance:** N/A



**Total Findings:** 5

**Finding 1**

The item has missing component(s) - Replace missing perspex windows

**Finding 2**

There is some graffiti present - Remove the graffiti

**Finding 3**

The communication panel is damaged - Repair / replace

**Finding 4**

There is/are bolt cap covers missing or damaged on the item - Replace missing or damaged bolt cap covers

**Finding 5**

There are trip hazards at the edges of the surface - Remove trip hazard

**i 9 - Low Risk**

**Item:** Litter Bin  
**Manufacturer:** Not Identified  
**Surface Type:** Grass  
**Item Quantity:** 3  
**Equipment Compliance:** N/A  
**Surface Area Compliance:** N/A



**Total Findings:** 2

**Finding 1**

Parts of the steel on this item have corroded excessively and the metal has perforated in places - Replace bin liner

**Finding 2**

The bin has been damaged - Monitor for any further deterioration and replace as required

**i** 8 - Low Risk

**Item:** Start Ramp  
**Manufacturer:** Not Identified  
**Surface Type:** Grass  
**Item Quantity:** 1  
**Equipment Compliance:** No  
**Surface Area Compliance:** Yes



**Total Findings:** 11

**Finding 1**

The riding surface has minor damage apparent - Monitor for any further deterioration and repair as required

**Finding 2**

The rear panels are missing - Replace

**Finding 3**

Cable ties are present and there are sharp projecting ends - Remove

**Finding 4**

A number of fixing(s) have worked loose - Secure all loose fixings

**Finding 5**

There is or are fixings missing on the item - Replace all missing fixings

**Finding 6**

There is/are inserts missing - Replace missing inserts

**Finding 7**

Joints between the riding / rolling surfaces shall not be greater than 5mm in contravention of the requirements of BS EN 14974 – 6.2.4 - Take corrective action to ensure that the gaps between the joints do not exceed 5mm

**Finding 8**

The barrier has not been extended at the upper part of the platform by at least 1000mm in contravention of the requirements of BS EN 14974 - 6.2.6 - Monitor - no reasonably practicable action given the risk assessment

**Finding 9**

The distance between the barrier and the platform exceeds 60mm in contravention of the requirements of BS EN 14974 - 6.2.6 - Monitor - no reasonably practicable action given the risk assessment

**Finding 10**

The height of the barrier is less than 1200mm in contravention of BS EN 14974 - 6.2.6. This height must be achieved all around the platform and at a maximum distance of 300mm from the front of the platform. - Monitor - no reasonably practicable action given the risk assessment

**Finding 11**

There is weed / vegetation growth within the surface - Remove weed / vegetation growth

**i 8 - Low Risk**

**Item:** Fun Box  
**Manufacturer:** Not Identified  
**Surface Type:** Concrete  
**Item Quantity:** 1  
**Equipment Compliance:** No  
**Surface Area Compliance:** Yes



**Total Findings:** 7

**Finding 1**

The side panel is missing - Replace

**Finding 2**

The riding surface has minor damage apparent - Monitor for any further deterioration and repair as required

**Finding 3**

There is or are fixings missing on the item - Replace all missing fixings

**Finding 4**

The ends of tubular parts / copings are not capped, in contravention of the requirements of BS EN 14974 - 6.1.8 - Ensure all coping ends are sealed

**Finding 5**

The item has exposed edges and corners with a radius of less than 3mm and fails the requirements of BS EN 14974 - Monitor - No action given the risk assessment

**Finding 6**

Joints between the riding / rolling surfaces shall not be greater than 5mm in contravention of the requirements of BS EN 14974 - 6.2.4 - Take corrective action to ensure that the gaps between the joints do not exceed 5mm

**Finding 7**

The kicker plate protrudes more than 5mm above the surrounding surface level, BS EN 14974 - 6.1.4 recommends a maximum of 5mm - Adjust height to ensure a maximum of 5mm change in level

**i** 9 - Low Risk

**Item:** End Transition & Wall Ramp  
**Manufacturer:** Not Identified  
**Surface Type:** Concrete  
**Item Quantity:** 1  
**Equipment Compliance:** No  
**Surface Area Compliance:** Yes



**Total Findings:** 12

**Finding 1**

The riding surface has minor damage apparent - Monitor for any further deterioration and repair as required

**Finding 2**

The end panels are missing - Replace

**Finding 3**

A number of fixing(s) have worked loose - Secure all loose fixings

**Finding 4**

There is or are fixings missing on the item - Replace all missing fixings

**Finding 5**

There is/are inserts missing - Replace missing inserts

**Finding 6**

There is broken glass present on site - Remove the broken glass and maintain the area

**Finding 7**

There is weed / vegetation growth within the surface - Remove weed / vegetation growth

**Finding 8**

Joints between the riding / rolling surfaces shall not be greater than 5mm in contravention of the requirements of BS EN 14974 – 6.2.4 - Take corrective action to ensure that the gaps between the joints do not exceed 5mm

**Finding 9**

The barrier has not been extended at the upper part of the platform by at least 1000mm in contravention of the requirements of BS EN 14974 - 6.2.6 - Monitor - no reasonably practicable action given the risk assessment

**Finding 10**

The distance between the barrier and the platform exceeds 60mm in contravention of the requirements of BS EN 14974 - 6.2.6 - Monitor - no reasonably practicable action given the risk assessment

**Finding 11**

The height of the barrier is less than 1200mm in contravention of BS EN 14974 - 6.2.6. This height must be achieved all around the platform and at a maximum distance of 300mm from the front of the platform. - Monitor - no reasonably practicable action given the risk assessment

**Finding 12**

The item has exposed edges and corners with a radius of less than 3mm and fails the requirements of BS EN 14974 - Monitor - No action given the risk assessment

**i** 2 - Very Low Risk

**Item:** Sign  
**Manufacturer:** Not Identified  
**Surface Type:** Grass  
**Item Quantity:** 1  
**Equipment Compliance:** N/A  
**Surface Area Compliance:** N/A



**Total Findings:** 1

**Finding 1**

This item is satisfactory - no work required -

**i** 8 - Low Risk

**Item:** Shoulder Press  
**Manufacturer:** Hags  
**Surface Type:** Grass Matrix Tiles  
**Item Quantity:** 1  
**Equipment Compliance:** No  
**Surface Area Compliance:** Yes



**Total Findings:** 2

**Finding 1**

The distance between the underside of the item and the ground is less than the 110mm required by BS EN 16630 - Monitor - No action given the risk assessment

**Finding 2**

BS EN 16630 - 4.3.1 states that fitness equipment shall be designed so when at rest, the equipment shall automatically adjust so that the equipment is ready for the next user - Service the item

**i** 4 - Very Low Risk

**Item:** Dip Station  
**Manufacturer:** Hags  
**Surface Type:** Grass Matrix Tiles  
**Item Quantity:** 1  
**Equipment Compliance:** Yes  
**Surface Area Compliance:** Yes

**Total Findings:** 1



**Finding 1**

This item is satisfactory - no work required -

**i** 5 - Very Low Risk

**Item:** Pull Up Station  
**Manufacturer:** Hags  
**Surface Type:** Grass Matrix Tiles  
**Item Quantity:** 1  
**Equipment Compliance:** Yes  
**Surface Area Compliance:** Yes

**Total Findings:** 1



**Finding 1**

There is no instruction label provided; an instruction label should be provided with each item of equipment in accordance with the requirements of BS EN 16630 - Provide appropriate instruction label/s

**i** 6 - Low Risk

**Item:** Hip Twister  
**Manufacturer:** Hags  
**Surface Type:** Grass Matrix Tiles  
**Item Quantity:** 1  
**Equipment Compliance:** No  
**Surface Area Compliance:** Yes



**Total Findings:** 1

**Finding 1**

The rotating user station is not appropriately marked with a guideline of user direction and/or the original position as required by BS EN 16630 - Monitor - No action given the risk assessment

**i** 6 - Low Risk

**Item:** Ski Stepper  
**Manufacturer:** Hags  
**Surface Type:** Grass Matrix Tiles  
**Item Quantity:** 1  
**Equipment Compliance:** Yes  
**Surface Area Compliance:** Yes



**Total Findings:** 1

**Finding 1**

This item is satisfactory - no work required -

**i** 8 - Low Risk

**Item:** Skier  
**Manufacturer:** Hags  
**Surface Type:** Grass Matrix Tiles  
**Item Quantity:** 1  
**Equipment Compliance:** No  
**Surface Area Compliance:** Yes



**Total Findings:** 1

**Finding 1**

The swinging movement of the footplate exceeds the maximum 55 degrees from the vertical required by BS EN 16630 - Monitor - No action given the risk assessment

**i** 6 - Low Risk

**Item:** Rower  
**Manufacturer:** Hags  
**Surface Type:** Grass Matrix Tiles  
**Item Quantity:** 1  
**Equipment Compliance:** Yes  
**Surface Area Compliance:** Yes



**Total Findings:** 1

**Finding 1**

This item is satisfactory - no work required -

**i** 8 - Low Risk

**Item:** Leg Press  
**Manufacturer:** Hags  
**Surface Type:** Grass Matrix Tiles  
**Item Quantity:** 1  
**Equipment Compliance:** Yes  
**Surface Area Compliance:** Yes

**Total Findings:** 1

**Finding 1**

This item is satisfactory - no work required -

## Findings information

<span style="font-size: 1.2em; font-weight: bold;">i</span> 8 - Low Risk (Finding 1)			
<b>Item:</b>	Ancillary Items - Site General	<b>Risk Level:</b>	L - Low Risk
<b>Manufacturer:</b>	Owner/Operator	<b>Surface:</b>	N/A
			
<b>Finding:</b> There is a discarded breeze block within the play area		<b>Action:</b> Remove from site	

**i** 9 - Low Risk (Finding 2)

**Item:** Ancillary Items - Site General  
**Manufacturer:** Owner/Operator

**Risk Level:** L - Low Risk  
**Surface:** N/A



**Finding:** The pathway to the skatepark has eroded and is slippery, making egress via this path extremely difficult

**Action:** Reinststate eroded area

**i** 0 - Risk Assessment not Undertaken (Finding 3)

**Item:** Ancillary Items - Site General  
**Manufacturer:** Owner/Operator

**Risk Level:** N - Risk Assessment not Undertaken  
**Surface:** N/A



**Finding:** There is some graffiti present on the skate ramps

**Action:** Remove the graffiti if deemed appropriate

**i** 8 - Low Risk (Finding 1)

**Item:** Gates - Gate - Self Closing  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Mixed Surface



**Finding:** There are openings that are less than 12mm that could trap or crush fingers

**Action:** Provide a 12mm gap throughout full range of motion at both sides of gate

**i** 6 - Low Risk (Finding 2)

**Item:** Gates - Gate - Self Closing  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Mixed Surface



**Finding:** There is / are post or end caps missing / damaged on the item

**Action:** Replace missing / damaged post or end caps

**i** 8 - Low Risk (Finding 3)

**Item:** Gates - Gate - Self Closing  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Mixed Surface



**Finding:** The gate is closing too quickly (less than 4 seconds)

**Action:** Take corrective action to ensure that the gate closes in 4-8 seconds from 90 degrees

**i** 6 - Low Risk (Finding 4)

**Item:** Gates - Gate - Self Closing  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Mixed Surface



**Finding:** The rubber buffer is missing from the latch plate

**Action:** Replace rubber buffer

**i** 6 - Low Risk (Finding 1)

**Item:** Fences - Fencing - Timber  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Grass



**Finding:** There are a number of loose posts around the fence

**Action:** Monitor for any further deterioration and reset as required

**i** 6 - Low Risk (Finding 2)

**Item:** Fences - Fencing - Timber  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Grass



**Finding:** Parts of the timber are rough or splintered

**Action:** Remove all rough or sharp edges

**i** 8 - Low Risk (Finding 3)

**Item:** Fences - Fencing - Timber  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Grass



**Finding:** There are areas or parts of the timber on the structure that have rotted

**Action:** Replace all affected timbers

**i** 8 - Low Risk (Finding 1)

**Item:** Fences - Fence - Chainlink  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Grass



**Finding:** The fence is severely damaged in places

**Action:** Repair or replace all affected sections

**i** 8 - Low Risk (Finding 2)

**Item:** Fences - Fence - Chainlink  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Grass



**Finding:** There are redundant cable ties attached to the fencing

**Action:** Remove

**i** 8 - Low Risk (Finding 1)

**Item:** Ancillary Items - Bench  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Grass



**Finding:** The area around the item has eroded and may become slippery

**Action:** Reinstate eroded area

**i** 4 - Very Low Risk (Finding 1)

**Item:** Activity Equipment - Activity Trail  
**Manufacturer:** Dylan Group Ltd

**Risk Level:** V - Very Low Risk  
**Surface:** Mixed Surface



**Finding:** There is/are bolt cap covers missing or damaged on the item

**Action:** Replace missing or damaged bolt cap covers

**i** 6 - Low Risk (Finding 2)

**Item:** Activity Equipment - Activity Trail  
**Manufacturer:** Dylan Group Ltd

**Risk Level:** L - Low Risk  
**Surface:** Mixed Surface



**Finding:** The surface has eroded in some areas and may be slippery in wet conditions

**Action:** Reinstate the surface

**i** 6 - Low Risk (Finding 1)

**Item:** Swings - 2 Bay (2 Flat, 2 Cradle)  
**Manufacturer:** Wicksteed Playgrounds

**Risk Level:** L - Low Risk  
**Surface:** Mixed Surface



**Finding:** There are gaps opening between the grass mat tiles

**Action:** Provide additional ties or secure / reinstate surface

**i** 8 - Low Risk (Finding 2)

**Item:** Swings - 2 Bay (2 Flat, 2 Cradle)  
**Manufacturer:** Wicksteed Playgrounds

**Risk Level:** L - Low Risk  
**Surface:** Mixed Surface



**Finding:** The grass mats are silted up and the soil is compacted; this may have an effect on the impact absorbing properties of the surface. Consideration should be given to HIC testing the surface to verify impact attenuating properties ( <https://playinspections.co.uk/inspection-services/safety-surface-testing/> )

**Action:** Contact our office for a quotation for this service

**i** 6 - Low Risk (Finding 3)

**Item:** Swings - 2 Bay (2 Flat, 2 Cradle)  
**Manufacturer:** Wicksteed Playgrounds

**Risk Level:** L - Low Risk  
**Surface:** Mixed Surface



**Finding:** The surface has subsided in some areas

**Action:** Monitor for any further deterioration and repair as required

**i** 8 - Low Risk (Finding 4)

**Item:** Swings - 2 Bay (2 Flat, 2 Cradle)  
**Manufacturer:** Wicksteed Playgrounds

**Risk Level:** L - Low Risk  
**Surface:** Mixed Surface



**Finding:** The surfacing dimensions are short and do not meet with the requirements of the current applicable standard

**Action:** Monitor - No action given the risk assessment

**i** 8 - Low Risk (Finding 5)

**Item:** Swings - 2 Bay (2 Flat, 2 Cradle)  
**Manufacturer:** Wicksteed Playgrounds

**Risk Level:** L - Low Risk  
**Surface:** Mixed Surface



**Finding:** The adjacent foliage is encroaching into the falling space of the equipment  
**Action:** Cut back and maintain

**i** 8 - Low Risk (Finding 6)

**Item:** Swings - 2 Bay (2 Flat, 2 Cradle)  
**Manufacturer:** Wicksteed Playgrounds

**Risk Level:** L - Low Risk  
**Surface:** Mixed Surface



**Finding:** The tree root forms a hard object within the impact area of the equipment in contravention of the requirements of BS EN 1176 Part 1  
**Action:** Monitor - No action given the risk assessment

**i** 4 - Very Low Risk (Finding 7)

**Item:** Swings - 2 Bay (2 Flat, 2 Cradle)  
**Manufacturer:** Wicksteed Playgrounds

**Risk Level:** V - Very Low Risk  
**Surface:** Mixed Surface



**Finding:** BS EN 1176 requires an additional 0.5m of unobstructed space at each end of the swing surfacing area. This is a relatively low risk finding and no remedial action is recommended at this point.

**Action:** Monitor - No action given the risk assessment

**i** 6 - Low Risk (Finding 8)

**Item:** Swings - 2 Bay (2 Flat, 2 Cradle)  
**Manufacturer:** Wicksteed Playgrounds

**Risk Level:** L - Low Risk  
**Surface:** Mixed Surface



**Finding:** The seat/s is / are too close to the frame as defined in BS EN 1176 Part 2

**Action:** Monitor - No action given the risk assessment

**i** 5 - Very Low Risk (Finding 9)

**Item:** Swings - 2 Bay (2 Flat, 2 Cradle)  
**Manufacturer:** Wicksteed Playgrounds

**Risk Level:** V - Very Low Risk  
**Surface:** Mixed Surface



**Finding:** The chain openings are in excess of the 8.6mm as recommended by BS EN 1176  
**Action:** Monitor - No action given the risk assessment

**i** 6 - Low Risk (Finding 10)

**Item:** Swings - 2 Bay (2 Flat, 2 Cradle)  
**Manufacturer:** Wicksteed Playgrounds

**Risk Level:** L - Low Risk  
**Surface:** Mixed Surface



**Finding:** The seats are too close to each other as defined in BS EN 1176 Part 2; this is a low risk failure and no remedial action is required  
**Action:** Monitor - No action given the risk assessment

**i** 6 - Low Risk (Finding 11)

**Item:** Swings - 2 Bay (2 Flat, 2 Cradle)  
**Manufacturer:** Wicksteed Playgrounds

**Risk Level:** L - Low Risk  
**Surface:** Mixed Surface



**Finding:** The tree canopy overhangs the equipment and is less than 2.0m away

**Action:** Lift tree canopy to ensure a minimum clearance of 2.0m from the equipment

**i** 6 - Low Risk (Finding 12)

**Item:** Swings - 2 Bay (2 Flat, 2 Cradle)  
**Manufacturer:** Wicksteed Playgrounds

**Risk Level:** L - Low Risk  
**Surface:** Mixed Surface



**Finding:** The paint is flaking off the metalwork

**Action:** Rub down and re-paint

**i** 6 - Low Risk (Finding 13)

**Item:** Swings - 2 Bay (2 Flat, 2 Cradle)  
**Manufacturer:** Wicksteed Playgrounds

**Risk Level:** L - Low Risk  
**Surface:** Mixed Surface




**Finding:** There is some notable evidence of chain wear

**Action:** Monitor for any further deterioration and replace when 40% worn

**i** 6 - Low Risk (Finding 14)

**Item:** Swings - 2 Bay (2 Flat, 2 Cradle)  
**Manufacturer:** Wicksteed Playgrounds

**Risk Level:** L - Low Risk  
**Surface:** Mixed Surface



**Finding:** There is some wear to the connecting links

**Action:** Monitor for any further deterioration and replace when 40% worn

**i** 6 - Low Risk (Finding 15)

**Item:** Swings - 2 Bay (2 Flat, 2 Cradle)  
**Manufacturer:** Wicksteed Playgrounds

**Risk Level:** L - Low Risk  
**Surface:** Mixed Surface




**Finding:** There is some wear to the chain bars

**Action:** Monitor for any further deterioration and replace when 40% worn

**i** 8 - Low Risk (Finding 16)

**Item:** Swings - 2 Bay (2 Flat, 2 Cradle)  
**Manufacturer:** Wicksteed Playgrounds

**Risk Level:** L - Low Risk  
**Surface:** Mixed Surface



**Finding:** The bush / bushes is / are worn or missing

**Action:** Replace worn or missing bushes

**i** 6 - Low Risk (Finding 17)

**Item:** Swings - 2 Bay (2 Flat, 2 Cradle)  
**Manufacturer:** Wicksteed Playgrounds

**Risk Level:** L - Low Risk  
**Surface:** Mixed Surface



**Finding:** There is some wear to the shackles.

**Action:** Monitor for any further deterioration and replace when 40% worn

**i** 8 - Low Risk (Finding 18)

**Item:** Swings - 2 Bay (2 Flat, 2 Cradle)  
**Manufacturer:** Wicksteed Playgrounds

**Risk Level:** L - Low Risk  
**Surface:** Mixed Surface



**Finding:** There are excessive chain tails

**Action:** Cut back excessive chain links

**i** 8 - Low Risk (Finding 19)

**Item:** Swings - 2 Bay (2 Flat, 2 Cradle)  
**Manufacturer:** Wicksteed Playgrounds

**Risk Level:** L - Low Risk  
**Surface:** Mixed Surface



**Finding:** There are excessive chain tails provided, however a minimum of 2 additional links should always be provided with crucifix connectors

**Action:** Cut back excess chain tails but ensure a minimum of 2 additional links remain through the crucifix

**i** 8 - Low Risk (Finding 20)

**Item:** Swings - 2 Bay (2 Flat, 2 Cradle)  
**Manufacturer:** Wicksteed Playgrounds

**Risk Level:** L - Low Risk  
**Surface:** Mixed Surface



**Finding:** Cable ties are present and there are sharp projecting ends

**Action:** Remove

**i** 0 - Risk Assessment not Undertaken (Finding 21)

**Item:** Swings - 2 Bay (2 Flat, 2 Cradle)  
**Manufacturer:** Wicksteed Playgrounds

**Risk Level:** N - Risk Assessment not Undertaken  
**Surface:** Mixed Surface



**Finding:** The fixings or components for this item were in excess of 2.5m above the standing surface and could not be fully accessed by the inspector. We have completed a visual inspection of the fixings from ground level but a maintenance inspection should be undertaken to assess the condition, security and wear of the components at intervals in accordance with the manufacturers recommendations.

**Action:** Inspect in accordance with the manufacturers recommendations

**i** 6 - Low Risk (Finding 1)

**Item:** Activity Equipment - Boat  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Grass



**Finding:** The surface has eroded in some areas and may be slippery in wet conditions  
**Action:** Reinststate the surface

**i** 6 - Low Risk (Finding 2)

**Item:** Activity Equipment - Boat  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Grass



**Finding:** There is some evidence of fire damage to the item  
**Action:** Monitor for any further deterioration and repair as required

**i** 10 - Low Risk (Finding 3)

**Item:** Activity Equipment - Boat  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Grass



**Finding:** There are areas or parts of the timber on the structure that have rotted

**Action:** Replace all affected timbers

**i** 6 - Low Risk (Finding 4)

**Item:** Activity Equipment - Boat  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Grass




**Finding:** There is some evidence of rot in the timber

**Action:** Monitor for any further deterioration and replace as required

**i** 8 - Low Risk (Finding 5)

**Item:** Activity Equipment - Boat  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Grass



**Finding:** The decking is damaged exposing ground fixings

**Action:** Repair affected areas

**i** 8 - Low Risk (Finding 1)

**Item:** Other - Free Standing Slide  
**Manufacturer:** Wicksteed Playgrounds

**Risk Level:** L - Low Risk  
**Surface:** Grass Matrix Tiles



**Finding:** The grass mats are silted up and the soil is compacted; this may have an effect on the impact absorbing properties of the surface. Consideration should be given to HIC testing the surface to verify impact attenuating properties ( <https://playinspections.co.uk/inspection-services/safety-surface-testing/> )

**Action:** Contact our office for a quotation for this service

**i** 5 - Very Low Risk (Finding 2)

**Item:** Other - Free Standing Slide  
**Manufacturer:** Wicksteed Playgrounds

**Risk Level:** V - Very Low Risk  
**Surface:** Grass Matrix Tiles



**Finding:** Fixing Pins have been installed in the impact areas of the grass mats

**Action:** Remove pins from impact areas

**i** 6 - Low Risk (Finding 3)

**Item:** Other - Free Standing Slide  
**Manufacturer:** Wicksteed Playgrounds

**Risk Level:** L - Low Risk  
**Surface:** Grass Matrix Tiles



**Finding:** There are gaps opening between the grass mat tiles

**Action:** Provide additional ties or secure / reinstate surface tiles

**i** 6 - Low Risk (Finding 4)

**Item:** Other - Free Standing Slide  
**Manufacturer:** Wicksteed Playgrounds

**Risk Level:** L - Low Risk  
**Surface:** Grass Matrix Tiles



**Finding:** The paint is flaking off the metalwork

**Action:** Rub down and re-paint

**i** 5 - Very Low Risk (Finding 5)

**Item:** Other - Free Standing Slide  
**Manufacturer:** Wicksteed Playgrounds

**Risk Level:** V - Very Low Risk  
**Surface:** Grass Matrix Tiles



**Finding:** There is / are toggle entrapment/s present in contravention of the recommendations set out in BS EN 1176 Part 1

**Action:** Monitor - No action given the risk assessment

**i** 8 - Low Risk (Finding 1)

**Item:** Rocking Equipment - Spring See-Saw  
**Manufacturer:** Kompan Ltd

**Risk Level:** L - Low Risk  
**Surface:** Mixed Surface




**Finding:** The grass has eroded within the impact area of the equipment and may not provide the necessary impact attenuating properties for the equipment fall height; the surface may also be slippery in wet weather

**Action:** Reinstate the grass or provide an all weather surface

**i** 8 - Low Risk (Finding 2)

**Item:** Rocking Equipment - Spring See-Saw  
**Manufacturer:** Kompan Ltd

**Risk Level:** L - Low Risk  
**Surface:** Mixed Surface



**Finding:** The surfacing has numerous stones present

**Action:** Ensure stones are removed and ground is suitable for use

**i** 4 - Very Low Risk (Finding 3)

**Item:** Rocking Equipment - Spring See-Saw  
**Manufacturer:** Kompan Ltd

**Risk Level:** V - Very Low Risk  
**Surface:** Mixed Surface




**Finding:** There is/are bolt cap covers missing or damaged on the item

**Action:** Replace missing or damaged bolt cap covers

**i** 6 - Low Risk (Finding 4)

**Item:** Rocking Equipment - Spring See-Saw  
**Manufacturer:** Kompan Ltd

**Risk Level:** L - Low Risk  
**Surface:** Mixed Surface



**Finding:** The spring mounting plate is slightly loose in the ground

**Action:** Monitor for any further deterioration and repair as required

**i** 8 - Low Risk (Finding 1)

**Item:** Activity Equipment - Multi Play (Junior)  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Grass Matrix Tiles



**Finding:** There are falls in excess of 600mm between adjacent components on the structure, in contravention of the recommendations set out in BS EN 1176 Part 1; 4.2.8.4

**Action:** Monitor - No action given the risk assessment

**i** 10 - Low Risk (Finding 2)

**Item:** Activity Equipment - Multi Play (Junior)  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Grass Matrix Tiles



**Finding:** The item fails to meet the requirements of BS EN 1176 Part 1 4.2.7.2 for head and neck entrapment between the log climber

**Action:** Consider removing entrapments

**i** 5 - Very Low Risk (Finding 3)

**Item:** Activity Equipment - Multi Play (Junior)  
**Manufacturer:** Not Identified

**Risk Level:** V - Very Low Risk  
**Surface:** Grass Matrix Tiles



**Finding:** There is/are finger entrapment/s above the net climber and the item fails to meet the requirements of BS EN 1176 Part 1 4.2.7.6 Entrapment of fingers

**Action:** Monitor - No action given the risk assessment

**i** 5 - Very Low Risk (Finding 4)

**Item:** Activity Equipment - Multi Play (Junior)  
**Manufacturer:** Not Identified

**Risk Level:** V - Very Low Risk  
**Surface:** Grass Matrix Tiles



**Finding:** The connecting links are in excess of 8.6mm and less than 12mm and fail the requirements of BS EN 1176 Part 1; clause 4.2.13, Chains

**Action:** Monitor - No action given the risk assessment

**i** 5 - Very Low Risk (Finding 5)

**Item:** Activity Equipment - Multi Play (Junior)  
**Manufacturer:** Not Identified

**Risk Level:** V - Very Low Risk  
**Surface:** Grass Matrix Tiles



**Finding:** The item fails to meet the requirements of BS EN 1176 Part 1 4.2.7.2 head and neck entrapment in the barriers and/or steps

**Action:** Monitor - No action given the risk assessment

**i** 8 - Low Risk (Finding 6)

**Item:** Activity Equipment - Multi Play (Junior)  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Grass Matrix Tiles



**Finding:** The grass mats are silted up and the soil is compacted; this may have an effect on the impact absorbing properties of the surface. Consideration should be given to HIC testing the surface to verify impact attenuating properties ( <https://playinspections.co.uk/inspection-services/safety-surface-testing/> )

**Action:** Contact our office for a quotation for this service

**i** 6 - Low Risk (Finding 7)

**Item:** Activity Equipment - Multi Play (Junior)  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Grass Matrix Tiles



**Finding:** There are gaps opening between the grass mat tiles

**Action:** Provide additional ties or secure / reinstate surface tiles

**i** 6 - Low Risk (Finding 8)

**Item:** Activity Equipment - Multi Play (Junior)  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Grass Matrix Tiles



**Finding:** The surface has subsided in some areas

**Action:** Monitor for any further deterioration and repair as required

**i** 9 - Low Risk (Finding 9)

**Item:** Activity Equipment - Multi Play (Junior)  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Grass Matrix Tiles



**Finding:** The rope has worn and wire strands are exposed

**Action:** Replace rope or net

**i** 6 - Low Risk (Finding 10)

**Item:** Activity Equipment - Multi Play (Junior)  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Grass Matrix Tiles



**Finding:** There is some wear to the shackles.

**Action:** Monitor for any further deterioration and replace when 40% worn

**i** 10 - Low Risk (Finding 11)

**Item:** Activity Equipment - Multi Play (Junior)  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Grass Matrix Tiles



**Finding:** The chain links are worn excessively (50%) and require renewing

**Action:** Replace worn chains

**i** 6 - Low Risk (Finding 12)

**Item:** Activity Equipment - Multi Play (Junior)  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Grass Matrix Tiles



**Finding:** The paint is flaking off the metalwork

**Action:** Rub down and re-paint

**i** 6 - Low Risk (Finding 13)

**Item:** Activity Equipment - Multi Play (Junior)  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Grass Matrix Tiles



**Finding:** The tree canopy overhangs the equipment and is less than 2.0m away

**Action:** Lift tree canopy to ensure a minimum clearance of 2.0m from the equipment

**i** 6 - Low Risk (Finding 14)

**Item:** Activity Equipment - Multi Play (Junior)  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Grass Matrix Tiles



**Finding:** There is some notable evidence of chain wear

**Action:** Monitor for any further deterioration and replace when 40% worn

**i** 6 - Low Risk (Finding 15)

**Item:** Activity Equipment - Multi Play (Junior)  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Grass Matrix Tiles



**Finding:** The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting / corroding

**Action:** Treat affected areas and repaint

**i** 8 - Low Risk (Finding 16)

**Item:** Activity Equipment - Multi Play (Junior)  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Grass Matrix Tiles



**Finding:** There is some evidence of rot in the timber

**Action:** Monitor for any further deterioration and replace as required

**i** 6 - Low Risk (Finding 17)

**Item:** Activity Equipment - Multi Play (Junior)  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Grass Matrix Tiles



**Finding:** The connecting lugs are showing signs of wear

**Action:** Monitor for any further deterioration and repair as required

**i** 6 - Low Risk (Finding 18)

**Item:** Activity Equipment - Multi Play (Junior)  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Grass Matrix Tiles



**Finding:** The timber has a number of splits/shakes or air cracks and this may affect the stability or allow water ingress which will accelerate the rotting process  
**Action:** Monitor to ensure the splits do not cross through fixing points of the structure and/or cause any instability

**i** 6 - Low Risk (Finding 19)

**Item:** Activity Equipment - Multi Play (Junior)  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Grass Matrix Tiles



**Finding:** Parts of the timber are rough or splintered  
**Action:** Remove all rough or sharp edges

**i** 6 - Low Risk (Finding 20)

**Item:** Activity Equipment - Multi Play (Junior)  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Grass Matrix Tiles



**Finding:** The fixing plates are not flush with the posts

**Action:** Rectify installation

**i** 6 - Low Risk (Finding 1)

**Item:** Activity Equipment - Climbing Frame  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Grass



**Finding:** The surface has subsided in some areas

**Action:** Monitor for any further deterioration and repair as required

**i** 10 - Low Risk (Finding 2)

**Item:** Activity Equipment - Climbing Frame  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Grass



**Finding:** The surface has eroded and the foundations are exposed

**Action:** Reinstall surrounding surfaces to cover the foundations

**i** 5 - Very Low Risk (Finding 3)

**Item:** Activity Equipment - Climbing Frame  
**Manufacturer:** Not Identified

**Risk Level:** V - Very Low Risk  
**Surface:** Grass



**Finding:** The item fails to meet the requirements of BS EN 1176 Part 1 4.2.7.2 for head and neck entrapment in the framework

**Action:** Monitor - No action given the risk assessment

**i** 6 - Low Risk (Finding 4)

**Item:** Activity Equipment - Climbing Frame  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Grass



**Finding:** The paint is flaking off the metalwork

**Action:** Rub down and re-paint

**i** 8 - Low Risk (Finding 1)

**Item:** Activity Equipment - Overhead Glider  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Grass Matrix Tiles



**Finding:** The surface has eroded and the foundations are exposed

**Action:** Reinstate surrounding surfaces to cover the foundations

**i** 6 - Low Risk (Finding 2)

**Item:** Activity Equipment - Overhead Glider  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Grass Matrix Tiles



**Finding:** There are gaps opening between the grass mat tiles

**Action:** Provide additional ties or secure / reinstate surface

**i** 6 - Low Risk (Finding 3)

**Item:** Activity Equipment - Overhead Glider  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Grass Matrix Tiles



**Finding:** The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting / corroding

**Action:** Treat affected areas and repaint

**i** 6 - Low Risk (Finding 4)

**Item:** Activity Equipment - Overhead Glider  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Grass Matrix Tiles



**Finding:** The paint is flaking off the metalwork

**Action:** Rub down and re-paint

 12 - Moderate Risk (Finding 5)

**Item:** Activity Equipment - Overhead Glider  
**Manufacturer:** Not Identified

**Risk Level:** M - Moderate Risk  
**Surface:** Grass Matrix Tiles



**Finding:** The connecting links are worn excessively (70%) and require renewing

**Action:** Replace

**i** 6 - Low Risk (Finding 6)

**Item:** Activity Equipment - Overhead Glider  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Grass Matrix Tiles



**Finding:** There is some notable evidence of chain wear

**Action:** Monitor for any further deterioration and replace when 40% worn

**i** 8 - Low Risk (Finding 7)

**Item:** Activity Equipment - Overhead Glider  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Grass Matrix Tiles



**Finding:** There is some wear to the chain bars

**Action:** Monitor for any further deterioration and replace when 40% worn

**i** 8 - Low Risk (Finding 8)

**Item:** Activity Equipment - Overhead Glider  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Grass Matrix Tiles



**Finding:** There is or are fixings missing on the item

**Action:** Replace all missing fixings

**i** 5 - Very Low Risk (Finding 9)

**Item:** Activity Equipment - Overhead Glider  
**Manufacturer:** Not Identified

**Risk Level:** V - Very Low Risk  
**Surface:** Grass Matrix Tiles



**Finding:** There is/are finger entrapment/s in the traveller and the item fails to meet the requirements of BS EN 1176 Part 1 4.2.7.6 Entrapment of fingers

**Action:** Monitor - No action given the risk assessment

**i** 6 - Low Risk (Finding 1)

**Item:** Ancillary Items - Teenage Shelter  
**Manufacturer:** Monster Play Systems

**Risk Level:** L - Low Risk  
**Surface:** Grass



**Finding:** The item has missing component(s)

**Action:** Replace missing perspex windows

**i** 0 - Risk Assessment not Undertaken (Finding 2)

**Item:** Ancillary Items - Teenage Shelter  
**Manufacturer:** Monster Play Systems

**Risk Level:** N - Risk Assessment not Undertaken  
**Surface:** Grass



**Finding:** There is some graffiti present

**Action:** Remove the graffiti

**i** 6 - Low Risk (Finding 3)

**Item:** Ancillary Items - Teenage Shelter  
**Manufacturer:** Monster Play Systems

**Risk Level:** L - Low Risk  
**Surface:** Grass



**Finding:** The communication panel is damaged

**Action:** Repair / replace

**i** 4 - Very Low Risk (Finding 4)

**Item:** Ancillary Items - Teenage Shelter  
**Manufacturer:** Monster Play Systems

**Risk Level:** V - Very Low Risk  
**Surface:** Grass



**Finding:** There is/are bolt cap covers missing or damaged on the item

**Action:** Replace missing or damaged bolt cap covers

**i** 8 - Low Risk (Finding 5)

**Item:** Ancillary Items - Teenage Shelter  
**Manufacturer:** Monster Play Systems

**Risk Level:** L - Low Risk  
**Surface:** Grass



**Finding:** There are trip hazards at the edges of the surface

**Action:** Remove trip hazard

**i** 9 - Low Risk (Finding 1)

**Item:** Ancillary Items - Litter Bin  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Grass



**Finding:** Parts of the steel on this item have corroded excessively and the metal has perforated in places

**Action:** Replace bin liner

**i** 6 - Low Risk (Finding 2)

**Item:** Ancillary Items - Litter Bin  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Grass



**Finding:** The bin has been damaged

**Action:** Monitor for any further deterioration and replace as required

**i** 6 - Low Risk (Finding 1)

**Item:** Wheeled Sports - Start Ramp  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Grass



**Finding:** The riding surface has minor damage apparent

**Action:** Monitor for any further deterioration and repair as required

**i** 8 - Low Risk (Finding 2)

**Item:** Wheeled Sports - Start Ramp  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Grass



**Finding:** The rear panels are missing

**Action:** Replace

**i** 8 - Low Risk (Finding 3)

**Item:** Wheeled Sports - Start Ramp  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Grass



**Finding:** Cable ties are present and there are sharp projecting ends

**Action:** Remove

**i** 6 - Low Risk (Finding 4)

**Item:** Wheeled Sports - Start Ramp  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Grass



**Finding:** A number of fixing(s) have worked loose

**Action:** Secure all loose fixings

**i** 8 - Low Risk (Finding 5)

**Item:** Wheeled Sports - Start Ramp  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Grass



**Finding:** There is or are fixings missing on the item

**Action:** Replace all missing fixings

**i** 4 - Very Low Risk (Finding 6)

**Item:** Wheeled Sports - Start Ramp  
**Manufacturer:** Not Identified

**Risk Level:** V - Very Low Risk  
**Surface:** Grass



**Finding:** There is/are inserts missing

**Action:** Replace missing inserts

**i** 5 - Very Low Risk (Finding 7)

**Item:** Wheeled Sports - Start Ramp  
**Manufacturer:** Not Identified

**Risk Level:** V - Very Low Risk  
**Surface:** Grass



**Finding:** Joints between the riding / rolling surfaces shall not be greater than 5mm in contravention of the requirements of BS EN 14974 – 6.2.4  
**Action:** Take corrective action to ensure that the gaps between the joints do not exceed 5mm

**i** 6 - Low Risk (Finding 8)

**Item:** Wheeled Sports - Start Ramp  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Grass



**Finding:** The barrier has not been extended at the upper part of the platform by at least 1000mm in contravention of the requirements of BS EN 14974 - 6.2.6  
**Action:** Monitor - no reasonably practicable action given the risk assessment

**i** 6 - Low Risk (Finding 9)

**Item:** Wheeled Sports - Start Ramp  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Grass



**Finding:** The distance between the barrier and the platform exceeds 60mm in contravention of the requirements of BS EN 14974 - 6.2.6

**Action:** Monitor - no reasonably practicable action given the risk assessment

**i** 6 - Low Risk (Finding 10)

**Item:** Wheeled Sports - Start Ramp  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Grass



**Finding:** The height of the barrier is less than 1200mm in contravention of BS EN 14974 - 6.2.6. This height must be achieved all around the platform and at a maximum distance of 300mm from the front of the platform.

**Action:** Monitor - no reasonably practicable action given the risk assessment

**i** 6 - Low Risk (Finding 11)

**Item:** Wheeled Sports - Start Ramp  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Grass



**Finding:** There is weed / vegetation growth within the surface

**Action:** Remove weed / vegetation growth

**i** 8 - Low Risk (Finding 1)

**Item:** Wheeled Sports - Fun Box  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Concrete



**Finding:** The side panel is missing

**Action:** Replace

**i** 8 - Low Risk (Finding 2)

**Item:** Wheeled Sports - Fun Box  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Concrete



**Finding:** The riding surface has minor damage apparent

**Action:** Monitor for any further deterioration and repair as required

**i** 8 - Low Risk (Finding 3)

**Item:** Wheeled Sports - Fun Box  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Concrete



**Finding:** There is or are fixings missing on the item

**Action:** Replace all missing fixings

**i** 8 - Low Risk (Finding 4)

**Item:** Wheeled Sports - Fun Box  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Concrete



**Finding:** The ends of tubular parts / copings are not capped, in contravention of the requirements of BS EN 14974 - 6.1.8

**Action:** Ensure all coping ends are sealed

**i** 6 - Low Risk (Finding 5)

**Item:** Wheeled Sports - Fun Box  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Concrete



**Finding:** The item has exposed edges and corners with a radius of less than 3mm and fails the requirements of BS EN 14974

**Action:** Monitor - No action given the risk assessment

**i** 5 - Very Low Risk (Finding 6)

**Item:** Wheeled Sports - Fun Box  
**Manufacturer:** Not Identified

**Risk Level:** V - Very Low Risk  
**Surface:** Concrete



**Finding:** Joints between the riding / rolling surfaces shall not be greater than 5mm in contravention of the requirements of BS EN 14974 – 6.2.4

**Action:** Take corrective action to ensure that the gaps between the joints do not exceed 5mm

**8 - Low Risk (Finding 7)**

**Item:** Wheeled Sports - Fun Box  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Concrete



**Finding:** The kicker plate protrudes more than 5mm above the surrounding surface level, BS EN 14974 - 6.1.4 recommends a maximum of 5mm

**Action:** Adjust height to ensure a maximum of 5mm change in level

**6 - Low Risk (Finding 1)**

**Item:** Wheeled Sports - End Transition & Wall Ramp  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Concrete



**Finding:** The riding surface has minor damage apparent

**Action:** Monitor for any further deterioration and repair as required

**i** 8 - Low Risk (Finding 2)

**Item:** Wheeled Sports - End Transition & Wall Ramp  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Concrete



**Finding:** The end panels are missing

**Action:** Replace

**i** 6 - Low Risk (Finding 3)

**Item:** Wheeled Sports - End Transition & Wall Ramp  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Concrete



**Finding:** A number of fixing(s) have worked loose

**Action:** Secure all loose fixings

**i** 8 - Low Risk (Finding 4)

**Item:** Wheeled Sports - End Transition & Wall Ramp  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Concrete



**Finding:** There is or are fixings missing on the item

**Action:** Replace all missing fixings

**i** 4 - Very Low Risk (Finding 5)

**Item:** Wheeled Sports - End Transition & Wall Ramp  
**Manufacturer:** Not Identified

**Risk Level:** V - Very Low Risk  
**Surface:** Concrete



**Finding:** There is/are inserts missing

**Action:** Replace missing inserts

**i** 9 - Low Risk (Finding 6)

**Item:** Wheeled Sports - End Transition & Wall Ramp  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Concrete



**Finding:** There is broken glass present on site

**Action:** Remove the broken glass and maintain the area

**i** 6 - Low Risk (Finding 7)

**Item:** Wheeled Sports - End Transition & Wall Ramp  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Concrete



**Finding:** There is weed / vegetation growth within the surface

**Action:** Remove weed / vegetation growth

**i** 5 - Very Low Risk (Finding 8)

**Item:** Wheeled Sports - End Transition & Wall Ramp  
**Manufacturer:** Not Identified

**Risk Level:** V - Very Low Risk  
**Surface:** Concrete



**Finding:** Joints between the riding / rolling surfaces shall not be greater than 5mm in contravention of the requirements of BS EN 14974 – 6.2.4  
**Action:** Take corrective action to ensure that the gaps between the joints do not exceed 5mm

**i** 6 - Low Risk (Finding 9)

**Item:** Wheeled Sports - End Transition & Wall Ramp  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Concrete



**Finding:** The barrier has not been extended at the upper part of the platform by at least 1000mm in contravention of the requirements of BS EN 14974 - 6.2.6  
**Action:** Monitor - no reasonably practicable action given the risk assessment

**i** 6 - Low Risk (Finding 10)

**Item:** Wheeled Sports - End Transition & Wall Ramp  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Concrete



**Finding:** The distance between the barrier and the platform exceeds 60mm in contravention of the requirements of BS EN 14974 - 6.2.6

**Action:** Monitor - no reasonably practicable action given the risk assessment

**i** 6 - Low Risk (Finding 11)

**Item:** Wheeled Sports - End Transition & Wall Ramp  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Concrete



**Finding:** The height of the barrier is less than 1200mm in contravention of BS EN 14974 - 6.2.6. This height must be achieved all around the platform and at a maximum distance of 300mm from the front of the platform.

**Action:** Monitor - no reasonably practicable action given the risk assessment

**6 - Low Risk (Finding 12)**

**Item:** Wheeled Sports - End Transition & Wall Ramp  
**Manufacturer:** Not Identified

**Risk Level:** L - Low Risk  
**Surface:** Concrete



**Finding:** The item has exposed edges and corners with a radius of less than 3mm and fails the requirements of BS EN 14974

**Action:** Monitor - No action given the risk assessment

**8 - Low Risk (Finding 1)**

**Item:** Outdoor Fitness Equipment - Shoulder Press  
**Manufacturer:** Hags

**Risk Level:** L - Low Risk  
**Surface:** Grass Matrix Tiles



**Finding:** The distance between the underside of the item and the ground is less than the 110mm required by BS EN 16630

**Action:** Monitor - No action given the risk assessment

**i** 8 - Low Risk (Finding 2)

**Item:** Outdoor Fitness Equipment - Shoulder Press  
**Manufacturer:** Hags

**Risk Level:** L - Low Risk  
**Surface:** Grass Matrix Tiles




**Finding:** BS EN 16630 - 4.3.1 states that fitness equipment shall be designed so when at rest, the equipment shall automatically adjust so that the equipment is ready for the next user  
**Action:** Service the item

**5 - Very Low Risk (Finding 1)**

**Item:** Outdoor Fitness Equipment - Pull Up Station  
**Manufacturer:** Hags

**Risk Level:** V - Very Low Risk  
**Surface:** Grass Matrix Tiles



**Finding:** There is no instruction label provided; an instruction label should be provided with each item of equipment in accordance with the requirements of BS EN 16630

**Action:** Provide appropriate instruction label/s

**6 - Low Risk (Finding 1)**

**Item:** Outdoor Fitness Equipment - Hip Twister  
**Manufacturer:** Hags

**Risk Level:** L - Low Risk  
**Surface:** Grass Matrix Tiles



**Finding:** The rotating user station is not appropriately marked with a guideline of user direction and/or the original position as required by BS EN 16630

**Action:** Monitor - No action given the risk assessment

**i** 8 - Low Risk (Finding 1)

**Item:** Outdoor Fitness Equipment - Skier  
**Manufacturer:** Hags

**Risk Level:** L - Low Risk  
**Surface:** Grass Matrix Tiles



**Finding:** The swinging movement of the footplate exceeds the maximum 55 degrees from the vertical required by BS EN 16630

**Action:** Monitor - No action given the risk assessment